

### Limit Micrometers SERIES 113

#### Measurement example



- Can be used as a Go/No-go gage by setting the upper and lower limits.
- Measuring faces: Carbide tipped



113-102

### SPECIFICATIONS

Metric					
Code No.	Range (mm)	Graduation (mm)	Maximum permissible error $J_{MPE}$ (μm)	Flatness (μm)	Parallelism (μm)
113-102	0 - 25	0.01	±3	0.6	3
113-103	25 - 50				

- Standard Accessories: Setting standard, 1 pc. (except for measuring range 0 to 25 mm and 0 to 1 in models)  
Spanner (200877), 1 pc.

### DIMENSIONS

